----- DATE: 5/09/19
MATERIAL SAFETY DATA SHEET PAGE: 1

SHIPPED FROM:

CLARIANT PLASTICS & COATING

CANADA, INC. MASTERBATCHES 2 LONE OAK COURT

TORONTO ONTARIO M9C 5R9

PHONE: 416-847-7000

FOR ALL EMERGENCIES 269-753-8434 PREPARED BY: PRODUCT SAFETY DEPARTMENT

CLARIANT WEBSITE: HTTP:\\WWW.CLARIANTMASTERBATCH.COM

PRODUCT DESCRIPTION: DC RVC-544 001.000% COLONIAL WHITE DC

PRODUCT CODE: 01DRV-283

\*\*\*\*\* MATERIAL SAFETY DATA SHEETS \*\*\*\*\*

THE ATTACHED MATERIAL SAFETY DATA SHEET (MSDS) IS AN IMPORTANT DOCUMENT. THE OSHA HAZARDOUS COMMUNICATION STANDARD REQUIRES US TO FORWARD A MSDS PRIOR TO OR ACCOMPANYING AN INITIAL SHIPMENT OF A PRODUCT AND THE "STANDARD" REQUIRES YOUR COMPANY TO KEEP THE MSDS ON FILE.

\*

IF YOU ARE NOT RESPONSIBLE FOR HEALTH AND SAFETY IN YOUR COMPANY PLEASE INSURE THAT YOUR HEALTH AND SAFETY MANAGER RECEIVES THIS DOCUMENT.

\*

THANK YOU.

HAZARDOUS MATERIAL IDENTIFICATION SYSTEM (HMIS)

HEALTH ---->1

FLAMMABILITY ---->0

REACTIVITY ---->0

PERSONAL PROTECTION -->E

-----DATE: 5/09/19
MATERIAL SAFETY DATA SHEET PAGE: 2

SHIPPED FROM:

CLARIANT PLASTICS & COATING

CANADA, INC. MASTERBATCHES 2 LONE OAK COURT

TORONTO ONTARIO M9C 5R9

PHONE: 416-847-7000

FOR ALL EMERGENCIES 269-753-8434
PREPARED BY: PRODUCT SAFETY DEPARTMENT

CLARIANT WEBSITE: HTTP:\\WWW.CLARIANTMASTERBATCH.COM

PRODUCT DESCRIPTION: DC RVC-544 001.000% COLONIAL WHITE DC

PRODUCT CODE: 01DRV-283

\_\_\_\_\_\_

SECTION I - PRODUCT INFORMATION:

-----

PRODUCT DESCRIPTION:

DC RVC-544 001.000% COLONIAL WHITE DC

PRODUCT CODE: 01DRV-283 VERSION NUMBER: 1 DATE: 5/09/19

CHEMICAL NAME/FAMILY:

COLORANT

SECTION II - HAZARDOUS INGREDIENTS/IDENTITY INFORMATION:

THIS PRODUCT CONTAINS, AS A COMPONENT, THE SUBSTANCE(S) LISTED BELOW WHICH IS IDENTIFIED AS A HAZARDOUS CHEMICAL UNDER THE CRITERIA OF THE OSHA HAZARD COMMUNICATION STANDARD 29CFR1910.1200 OSHA HAZARD COMMUNICATION STANDARD 29CFR 1910.1200.

		USHA	ACGIH		
CAS		$\mathtt{PEL}$	${ t TLV}$	OTHER	DOES NOT
NUMBER	DESCRIPTION	MG/M3	MG/M3	LIMITS	EXCEED(%)
68186-90-3	CHROME ANTIMONY TITANIUM	_	_	_	3.05
CRCMPD	CHROMIUM (III) COMPOUND	0.5	0.5	_	3.05
SBCMPD	ANTIMONY & COMPOUNDS (AS SE	3) 0.5	0.5	_	3.05
7440-36-0	ANTIMONY (SB) METAL	0.5	0.5	_	.31
7440-47-3	CHROMIUM AS CR	0.5	0.5	_	.12
68412-38-4	C.I. PIGMENT YELLOW 164				.31
13463-67-7	TITANIUM DIOXIDE (DUST)	10.0	10.0	_	78.65
21645-51-2	ALUMINUM HYDROXIDE (AS AL)	N.E.	10.0	_	3.03
7631-86-9	SILICON DIOXIDE, AMORPHOUS	6.0	10.0	_	4.75

SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS:

BOILING POINT: N.A.

SPECIFIC GRAVITY: 3.8 - 4.3 VAPOR PRESSURE: N.A.

MELTING POINT: Non Determined

VAPOR DENSITY: N.A.
EVAPORATION RATE: N.A.
SOLUBILITY IN WATER: INSOLUBLE

APPEARANCE AND ODOR: COLORED DRY POWDER - NO SIGNIFICANT ODOR

SECTION IV - FIRE AND EXPLOSION HAZARD DATA:

MATERIAL SAFETY DAT

CLARIANT PLASTICS & COATING CANADA, INC. MASTERBATCHES

2 LONE OAK COURT

TORONTO ONTARIO M9C 5R9

PHONE: 416-847-7000

FOR ALL EMERGENCIES 269-753-8434 PREPARED BY: PRODUCT SAFETY DEPARTMENT

CLARIANT WEBSITE: HTTP:\\WWW.CLARIANTMASTERBATCH.COM

PRODUCT DESCRIPTION: DC RVC-544 001.000% COLONIAL WHITE DC

PRODUCT CODE: 01DRV-283

\_\_\_\_\_\_

SECTION IV - FIRE AND EXPLOSION HAZARD DATA:

FLASH POINT (METHOD USED):

THERE IS A COMPONENT IN THIS PRODUCT WITH A FLASH POINT OF 110 C. THE METHOD USED TO DETERMINE THIS IS: SCC ALL OTHER COMPONENTS USED IN THIS PRODUCT EITHER HAVE A HIGHER FLASH

POINT OR ARE NOT COMBUSTIBLE AND DO NOT HAVE A FLASH POINT.

EXTINGUISHING MEDIA:

USE WATER FOG, FOAM OR DRY CHEMICAL

SPECIAL FIRE FIGHTING PROCEDURES:

EQUIP FIREFIGHTERS WITH SELF-CONTAINED BREATHING APPARATUS (SCBA) AND TURN-OUT GEAR.

UNUSUAL FIRE AND EXPLOSION HAZARDS:

ORGANIC DUSTS HAVE POTENTIAL TO BE EXPLOSIVE WITH STATIC SPARK OR FLAME. MAINTAIN GOOD HOUSEKEEPING FOR CONTROL OF DUST.

\_\_\_\_\_\_

SECTION V - REACTIVITY DATA:

-----

STABILITY: STABLE -> X UNSTABLE ->

STABILITY (CONDITIONS TO AVOID):

NONE

INCOMPATILBILITY (MATERIALS TO AVOID):

AVOID CONTACT WITH STRONG ALKALI, AMINES.

HAZARDOUS DECOMPOSITION OR BYPRODUCTS:

THERMAL DECOMPOSITION PRODUCTS MAY INCLUDE HAZARDOUS FUMES OF TITANIUM OXIDE.

HAZARDOUS POLYMERIZATION: WILL OCCUR -> WILL NOT OCCUR -> X

HAZARDOUS POLYMERIZATION (CONDITIONS TO AVOID):

N/A

\_\_\_\_\_

SECTION VI - HEALTH HAZARD DATA:

MATERIAL SAFETY DATA SHEET

SHIPPED FROM:

CLARIANT PLASTICS & COATING

CANADA, INC. MASTERBATCHES 2 LONE OAK COURT

TORONTO ONTARIO M9C 5R9

PHONE: 416-847-7000

FOR ALL EMERGENCIES 269-753-8434 PREPARED BY: PRODUCT SAFETY DEPARTMENT

CLARIANT WEBSITE: HTTP:\\WWW.CLARIANTMASTERBATCH.COM

DATE: 5/09/19

PAGE: 4

PRODUCT DESCRIPTION: DC RVC-544 001.000% COLONIAL WHITE DC

PRODUCT CODE: 01DRV-283

\_\_\_\_\_\_

SECTION VI - HEALTH HAZARD DATA:

-----

HEALTH HAZARDS (ACUTE AND CHRONIC):

HEALTH HAZARD: INHALATION

SHORT TERM OVEREXPOSURE BY IHALATION TO TITANIUM DIOXIDE MAY CAUSE IRRITATION OF NOSE, THROAT, AND LUNGS WITH COUGH, DIFFICULTY BREATHING OR SHORTNESS OF BREATH. STUDIES SHOWED THAT EMPLOYEES WHO HAD BEEN EXPOSED TO TITANIUM DIOXIDE WERE AT NO GREATER RISK OF DEVELOPING LUNG CANCER THAN

WERE EMPLOYEES WHO HAD NOT BEEN EXPOSED TO TITANIUM DIOXIDE.

INHALATION OF AMORPHOUS SILICA MAY CAUSE DRYING OF MUCOUS MEMBRANES AND IRRITATION OF NOSE, THROAT, AND LUNGS WITH NOSEBLEEDS, COUGH AND DIFFICULTY

BREATHING OR SHORTNESS OF BREATH.

HEALTH HAZARD: SKIN

MAY CAUSE IRRITATION TO SKIN

HEALTH HAZARD: INGESTION

INGESTION MAY RESULT IN GASTRIC DISTURBANCES

HEALTH HAZARD: EYE CONTACT

CONTACT WITH EYE MAY CAUSE EYE IRRITATION

\_\_\_\_\_\_

IS ANY CHEMICAL IN THIS PRODUCT AT A CONCENTRATION OF 0.1 % OR MORE CLASSIFIED AS A CARCINOGEN BY IARC, NTP, OR OSHA? NO

-----

SIGNS AND SYMPTOMS OF EXPOSURE:

\* THE FOLLOWING INFORMATION PROVIDED ON THE BELOW HAZARDOUS INGREDIENT(S) APPLIES TO THE INGREDIENT(S) IN THE PURE DRY FORM.

CHROME ANTIMONY TITANIUM RUTILE: MAY CAUSE EYE, SKIN AND RESPIRATORY TRACT IRRITATION. PROLONGED INHALATION MAY CAUSE LUNG DAMAGE.

PIGMENT YELLOW 164: MAY CAUSE EYE, SKIN, AND RESPIRATORY TRACT IRRITATION. ROUTES OF ENTRY: INGESTION, INHALATION.

AMOROPHOUS SILICA: OVEREXPOSURE MAY CAUSE TISSUE RESPONSE IN THE LUNG WHICH IN SEVERE CASES CAN RESULT IN PULMONARY FIBROSIS (PNEUMOCONIOSIS).

MATERIAL SAFETY DATA SHEET PAGE: 5/09/19

SHIPPED FROM:

CLARIANT PLASTICS & COATING

CANADA, INC. MASTERBATCHES 2 LONE OAK COURT

TORONTO ONTARIO M9C 5R9

PHONE: 416-847-7000

FOR ALL EMERGENCIES 269-753-8434 PREPARED BY: PRODUCT SAFETY DEPARTMENT

CLARIANT WEBSITE: HTTP:\\WWW.CLARIANTMASTERBATCH.COM

PRODUCT DESCRIPTION: DC RVC-544 001.000% COLONIAL WHITE DC

PRODUCT CODE: 01DRV-283

\_\_\_\_\_\_

SECTION VI - HEALTH HAZARD DATA: (CONT)

TITANIUM DIOXIDE: MAY CAUSE MECHANICAL EYE IRRITATION. LONG TERM EXPOSURE TO AIRBORNE DUST MAY CAUSE LUNG DAMAGE.

MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE:

\* THE FOLLOWING INFORMATION PROVIDED ON THE BELOW HAZARDOUS INGREDIENT(S) APPLIES TO THE INGREDIENT(S) IN THE PURE DRY FORM.

CHROME ANTIMONY TITANIUM RUTILE: RESPIRATORY AND SKIN DISORDERS AGGRAVATED BY DUST.

PIGMENT YELLOW 164: SKIN AND RESPIRATORY DISORDERS.

AMOROPHOUS SILICA: NONE KNOWN TITANIUM DIOXIDE: NONE KNOWN

EMERGENCY FIRST AID: INHALATION

REMOVE TO CLEAN, FRESH AIR AND TREAT SYMPTOMATICALLY.

EMERGENCY FIRST AID: SKIN

REMOVE CONTAMINATED CLOTHING AND SHOES IMMEDIATELY. WASH WITH SOAP OR MILD DETERGENT AND LARGE AMOUNTS OF WATER UNTIL NO EVIDENCE OF CHEMICAL REMAINS (AT LEAST 15 - 20 MINUTES). GET MEDICAL ATTENTION IMMEDIATELY.

EMERGENCY FIRST AID: INGESTION

IF CONSCIOUS, GIVE WATER AND THEN INDUCE VOMITING. NEVER GIVE FLUIDS OR INDUCE VOMITING IF THE VICTIM IS UNCONSCIOUS OR HAVING CONVULSIONS. GET IMMEDIATE MEDICAL ATTENTION.

EMERGENCY FIRST AID: EYE CONTACT

WASH EYES IMMEDIATELY WITH LARGE AMOUNTS OF WATER OR NORMAL SALINE, OCCASIONALLY LIFTING UPPER AND LOWER LIDS, UNTIL NO EVIDENCE OF CHEMICAL REMAINS (AT LEAST 15 - 20 MINUTES). GET MEDICAL ATTENTION IMMEDIATELY.

-----

SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE:

\_\_\_\_\_\_

HANDLING: SPILLAGE

SPILLS SHOULD BE PLACED IN SUITABLE CONTAINERS FOR DISPOSAL IN A LICENSED

----- DATE: 5/09/19
MATERIAL SAFETY DATA SHEET PAGE: 6

SHIPPED FROM:

CLARIANT PLASTICS & COATING

CANADA, INC. MASTERBATCHES

2 LONE OAK COURT

TORONTO ONTARIO M9C 5R9

PHONE: 416-847-7000

FOR ALL EMERGENCIES 269-753-8434 PREPARED BY: PRODUCT SAFETY DEPARTMENT

CLARIANT WEBSITE: HTTP:\\WWW.CLARIANTMASTERBATCH.COM

PRODUCT DESCRIPTION: DC RVC-544 001.000% COLONIAL WHITE DC

PRODUCT CODE: 01DRV-283

\_\_\_\_\_\_

SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE: (CONT)

FACILITY. WEAR APPROPRIATE RESPRITORY PROTECTION AND PROTECTIVE CLOTHING

AND PROVIDE ADEQUATE VENTILATION DURING CLEAN-UP.

HANDLING: WASTE DISPOSAL

INCINERATE OR BURY IN A LICENSED FACILITY. DO NOT DISCHARGE INTO

WATERWAYS OR SEWER WITHOUT PROPER AUTHORITY.

HANDLING: STORAGE

AVOID GENERATING DUST. AVOID CONTACT WITH EYES, SKIN, OR CLOTHING. WASH

THOROUGHLY AFTER HANDLING. STORE IN A DRY WELL VENTILATED AREA. KEEP

CONTAINER TIGHTLY CLOSED.

HANDLING: OTHER PRECAUTIONS

USE UNDER WELL-VENTILATED CONDITIONS AND RECOMMEND THAT EMPLOYEES WASH

THOROUGHLY AFTER HANDLING PRODUCT.

-----

SECTION VIII - CONTROL MEASURES:

-----

CONTROL: RESPIRATORY PROTECTION

IN DUSTY ATMOSPHERES USE NIOSH/MSHA APPROVED RESPIRATORS

CONTROL: VENTILATION

LOCAL EXHAUST VENTILATION AS NECESSARY TO CONTROL DUST AS APPLICABLE.

CONTROL: GLOVES

LEATHER OR OTHER NON-PERMEABLE GLOVES.

CONTROL: EYE PROTECTION

GOGGLES

CONTROL: OTHER CLOTHING

EYE WASH STATION.

CONTROL: WORK/HYGIENE

DO NOT EAT, DRINK, OR SMOKE IN WORK AREAS. WASH THOROUGHLY WITH SOAP AND

WATER AFTER HANDLING.

\_\_\_\_\_\_

SHIPPED FROM:

CLARIANT PLASTICS & COATING

CANADA, INC. MASTERBATCHES

2 LONE OAK COURT

TORONTO ONTARIO M9C 5R9

PHONE: 416-847-7000

FOR ALL EMERGENCIES 269-753-8434 PREPARED BY: PRODUCT SAFETY DEPARTMENT

CLARIANT WEBSITE: HTTP:\\WWW.CLARIANTMASTERBATCH.COM

PRODUCT DESCRIPTION: DC RVC-544 001.000% COLONIAL WHITE DC

PRODUCT CODE: 01DRV-283

## SECTION IX - OTHER REGULATORY INFORMATION:

SARA - THIS PRODUCT CONTAINS THE FOLLOWING TOXIC CHEMICAL(S) SUBJECT TO THE REPORTING OF SECTION 313 OF TITLE III OF THE SUPERFUND AMENDMENTS AND REAUTHORIZATION ACT OF 1986 AND 40 CFR PART 372: THIS INFORMATION SHOULD BE INCLUDED IN ALL MSDS'S THAT ARE COPIED AND DISTRIBUTED FOR THIS MATERIAL.

DOES NOT

CAS # EXCEED(%) DESCRIPTION CRCMPD 3.05 CHROMIUM (III) COMPOUND SBCMPD 3.36 ANTIMONY COMPOUND 7440-36-0 .37 ANTIMONY (SB) METAL 7440-47-3 .12 CHROMIUM (III) AS (CR) MNCMPD .31 MANGANESE COMPOUND 7439-96-5 .02 MANGANESE (MN)

TSCA - ALL INGREDIENTS USED TO PRODUCE THE ABOVE FORMULATION ARE IN COMPLIANCE WITH THE TOXIC SUBSTANCES AND CONTROL ACT INVENTORY AS REQUIRED BY FEDERAL LAW.

## SECTION X - STATE REGULATORY INFORMATION:

\_\_\_\_\_\_

CA PROPOSITION 65: WARNING - ANY COMPONENT OF THIS PRODUCT WHICH CONTAINS MATERIALS KNOWN TO THE STATE OF CALIFORNIA TO CAUSE CANCER ARE LISTED BELOW:

PLEASE NOTE IT IS THE RESPONSIBILITY OF THE END USER TO DETERMINE IF ITS FINISHED PRODUCTS REQUIRE LABELING UNDER CALIFORNIA PROPOSITION 65. HTTP://WWW.OEHHA.CA.GOV/PROP65/PROP65 LIST/NEWLIST.HTML LEAD

HEXAVALENT CHROMIUM

CA PROPOSITION 65: WARNING - ANY COMPONENT OF THIS PRODUCT WHICH CONTAINS MATERIALS KNOWN TO THE STATE OF CALIFORNIA TO CAUSE DEVELOPMENTAL AND REPRODUCTIVE TOXICANT HARM ARE LISTED BELOW:

PLEASE NOTE IT IS THE RESPONSIBILITY OF THE END USER TO DETERMINE IF ITS FINISHED PRODUCTS REQUIRE LABELING UNDER CALIFORNIA PROPOSITION 65. HTTP://WWW.OEHHA.CA.GOV/PROP65/PROP65 LIST/NEWLIST.HTML

HEXAVALENT CHROMIUM

MATERIAL SAFETY DATA SHEET PAGE: 8

SHIPPED FROM:

CLARIANT PLASTICS & COATING CANADA, INC. MASTERBATCHES

2 LONE OAK COURT

TORONTO ONTARIO M9C 5R9

PHONE: 416-847-7000

FOR ALL EMERGENCIES 269-753-8434 PREPARED BY: PRODUCT SAFETY DEPARTMENT

CLARIANT WEBSITE: HTTP:\\WWW.CLARIANTMASTERBATCH.COM

PRODUCT DESCRIPTION: DC RVC-544 001.000% COLONIAL WHITE DC

PRODUCT CODE: 01DRV-283

\_\_\_\_\_\_

SECTION X - STATE REGULATORY INFORMATION: (CONT)

\_\_\_\_\_\_

CANADIAN WHMIS: ANY COMPONENT OF THIS PRODUCT WHICH IS A HAZARDOUS CHEMICAL AS GIVEN IN WHMIS IS SHOWN BELOW:

HTTP://WWW.CSST.QC.CA/EN/PREVENTION/REPTOX/PAGES/LIST-WHMIS-CAS-50-84.ASPX NONE

FLORIDA: ANY COMPONENT OF THIS PRODUCT WHICH IS A HAZARDOUS CHEMICAL CHEMICAL AS LISTED IN THE FLORIDA IS SHOWN BELOW:

MASSACHUSETTS: ANY COMPONENT OF THIS PRODUCT WHICH IS A HAZARDOUS CHEMICAL CHEMICAL AS LISTED IN THE MASSACHUSETTS SUBSTANCE LIST IS SHOWN BELOW:

NONE

NEW JERSEY: NON-HAZARDOUS INGREDIENTS ARE BEING WITH HELD AS TRADE SECRET INFORMATION. ANY COMPONENT OF THIS PRODUCT WHICH IS A HAZARDOUS CHEMICAL AS LISTED ON THE NEW JERSEY HAZARDOUS LIST IS GIVEN IN SECTION II OF THIS MSDS. ANY LISTED CHEMICALS NOT SHOWN IN SECTION II ARE AS FOLLOWS:

NONE

PENNSYLVANIA: NON-HAZARDOUS INGREDIENTS ARE BEING WITH HELD AS TRADE SECRET INFORMATION. ANY COMPONENT OF THIS PRODUCT WHICH IS A HAZARDOUS CHEMICAL AS LISTED ON THE PENNSYLVANIA HAZARDOUS LIST IS GIVEN IN SECTION II OF THIS MSDS. ANY LISTED CHEMICALS NOT SHOWN IN SECTION II ARE AS FOLLOWS:

NONE

RHODE ISLAND:ANY COMPONENT OF THIS PRODUCT WHICH IS A HAZARDOUS CHEMICAL CHEMICAL AS LISTED IN THE RHODE ISLAND SUBSTANCE LIST IS SHOWN IN SECTION II OF THIS MSDS. ANY LISTED CHEMICALS NOT SHOWN IN SECTION II ARE AS FOLLOWS:

THIS INFORMATION IS ACCURATE AND RELIABLE TO THE BEST OF OUR KNOWLEDGE. IT IS FURNISHED WITHOUT WARRANTY, EXPRESSED OR IMPLIED. CLARIANT CORPORATION ASSUMES NO LEGAL RESPONSIBILITY FOR THE USE OF, OR RELIANCE UPON, THESE DATA FOR HAZARDS WHICH MIGHT BE ASSOCIATED WITH THE USE OF THIS

----- DATE: 5/09/19
MATERIAL SAFETY DATA SHEET PAGE: 9

SHIPPED FROM:

CLARIANT PLASTICS & COATING CANADA, INC. MASTERBATCHES

2 LONE OAK COURT

TORONTO ONTARIO M9C 5R9

PHONE: 416-847-7000

FOR ALL EMERGENCIES 269-753-8434 PREPARED BY: PRODUCT SAFETY DEPARTMENT

CLARIANT WEBSITE: HTTP:\\WWW.CLARIANTMASTERBATCH.COM

PRODUCT DESCRIPTION: DC RVC-544 001.000% COLONIAL WHITE DC

PRODUCT CODE: 01DRV-283

MATERIAL OR FOR THE RESULTS OBTAINED. IT IS THE RESPONSIBILITY OF THE USER TO COMPLY WITH ALL APPLICABLE LAWS AND REGULATIONS.